PARTS LIST

2 3/8" SIZES

PART NUMBER

PART

N-2

NUT

GR8 Bearing Washer

T-113

BEARING

P11

BAIL

W-4 Shoulder washer

"Shoulder" of S-5 Shank

S-5

SHANK

S-6 SAFETY SPRING

-8-7

SLEEVE

B-8

BODY

334

O-RING

"INSIDE TAPER"
WHERE THE WORK IS
DONE

NEEDS LUBRICATION!

THE MURPHY FAST PLUG

PARTS LIST

2 7/8"and 3 1/2" SIZES

PART NUMBER PART NAME

N-12 ----NUT

W-13--- BEARING WASHER T-151-----BEARING

P-22MY-----HINGED BAIL W-14--SHOULDER WASHER

S-15 ----SHANK

S-16--HEAVY DUTY SPRING

S-17----SLEEVE

B-18-----BODY

INSIDE TAPER WHERE THE WORK IS

DONE

NEEDS LUBRICATION THE MURPHY FAST PLUGTEN

www.murphyfastplug.com